Loss of power in Right hand turns Posted by Lowco17 - 17 Jan 2015 17:28

First day at the track with a new build car.

Car is hard to start when cold, but starts fine when it has been warmed up. Idle is a little inconsistent. On the track it will lose all power coming out of a sharp right hand turn and partial power in a sweeping right hand turn. It is fine in the straights and in and after left hand turns.

I have replaced both Hall effect sensors, the TPS and the DME with no change.

Does anyone have any ideas? Any help is much appreciated.